

# Bureau International des Containers et du Transport Intermodal (B.I.C.)

Reparaciones Tecnicas de Contenedores S.L.  
C/Valdemoro N-16 1-B  
28320 Pinto  
Spain

## CERTIFICATE OF REGISTRATION OF CONTAINER CODE

In accordance with ISO Standard 6346, Customs Conventions and BIC Registration terms,  
The Bureau International des Containers hereby certifies that the BIC Code:

**RETU**

has been duly registered by the BIC and assigned to :

Reparaciones Tecnicas de Contenedores S.L.

**Certificate No. RETU-1616**

**2016**

The registered code shall apply only for containers owned/operated by the company named above and remains valid for through **15 March 2017**. In January 2017 a renewal notice and associated invoice shall be issued. Please ensure prompt return and payment to ensure continued validity of this code. Should the company name, address or ownership status change, please notify the BIC at the postal or email address or shown below.

Freight container prefix registration with the BIC is required by ISO standard 6346 and by the National Customs Administrations according to both Customs Convention on Containers (CCC-1972, revised 2008) and Istanbul Convention (1990, revised 2010). This grants the benefits of free circulation and temporary admission for containers displaying an owner's code registered with the BIC.

**Important notice: Consequences of the official registration of a BIC-code** Extract of the Registration Procedures, (for more information please consult the official annual CONTAINERS BIC-Code Register or the website [www.bic-code.org](http://www.bic-code.org))  
Each container marked with a code "- - - U" is officially and worldwide known to be owned - or operated (see 8.1.2) - by the code holder as recorded in BIC Register, with all the related responsibility (legal, commercial, damage, insurance, etc...) of such ownership.  
**After initial registration, this international code protection is subject to the payment of a yearly renewal fee** (as per tariff published each year in the CONTAINERS BIC-Code Register).  
Non-payment of the renewal fee will result in the **cancellation of this code protection within a period of 6 months**, confirmed by a registered letter, and with information to the controlling authorities worldwide. In case of transfer of ownership of such container(s), responsibility shall remain with above mentioned code holder until the time when :  
- the code marking is removed from each and every container.  
or - the code marking is changed for another - duly registered with BIC - held by the new owner (see 8.1.7)  
or - the code marking remains unchanged but its ownership has been duly transferred to another entity (see 8.1.3.d).

Jan 20, 2016

*Certificate issued by*


Tiana Randriamose  
Coding Department  
[tra@bic-code.org](mailto:tra@bic-code.org)

41, rue Réaumur – FR 75003 Paris  
[www.bic-code.org](http://www.bic-code.org)

Tél. : +33 (0)1 47 66 03 90 – Fax : +33 (0)1 47 66 08 91  
e-mail : [tra@bic-code.org](mailto:tra@bic-code.org)

SIRET : 784 330 193 00045 – APE 9412Z

(ASSOCIATION SANS BUT LUCRATIF FONDÉE EN 1933 SOUS LES AUSPICES DE LA CHAMBRE DE COMMERCE INTERNATIONALE)  
(ESTABLISHED IN 1933 UNDER THE AUSPICES OF THE INTERNATIONAL CHAMBER OF COMMERCE AS NON-PROFIT ASSOCIATION)



2016

**Certificate No. RETU-1616**